

SECTION 7

TERMINAL FACILITIES

7.3 JETWAY ACCESS DOORS *(rev. 4/2010)*

Exterior doors providing access to jetways are not to be blocked open. This can cause severe damage to building sprinkler systems and have negative effects on building air handling systems, particularly in winter months. Additional energy costs associated with this type of activity can be substantial. The cost of repairs attributed to improper manipulation of access doors will be billed to the air carrier responsible for the damage.